

KILOTECH

KIN 500

KWS 2200-15 / 30 / 60

KWS CY-60 / 150 / 300

KWS VET 250

MAN02212019

Contents subject to change without notice



www.kilotech.com

Table of Contents

| | |
|------------------------------------|----|
| Table of Contents..... | 2 |
| Introduction..... | 2 |
| General Precautions | 3 |
| Specifications..... | 4 |
| Specifications..... | 5 |
| Unpacking..... | 6 |
| Contents | 6 |
| Dimensions..... | 7 |
| Power | 7 |
| Display & Keypad Definitions | 8 |
| Key Descriptions..... | 9 |
| Summary of Keys / Functions..... | 10 |
| Normal Weighing Mode | 11 |
| Error Codes..... | 12 |
| Programming Symbols..... | 12 |

Introduction

Thank you for choosing a Kilotech Scale. We appreciate your business and hope that you will enjoy using your scale. Should you require Technical Support, please contact your local dealer from whom you have purchased.

General Precautions

| | |
|---|--|
| Avoid lengthy exposure to heat or cold | Allow the scale to acclimate to normal room temperature before use |
| Allow sufficient warm up time | Turn the scale on and wait for a few minutes to allow the internal components a chance to stabilize before weighing |
| Do not leave a load or weight on a scale for a prolonged period of time | Might damage load cell |
| Do not tamper with the scale yourself | This will void the warranty. Contact your local distributor or Kilotech directly to properly repair your scale |
| Do not overload beyond the maximum weight limit | |
| Do not pull the plug by its cord when unplugging | |
| Do not use the scale near fire or corrosive gas | |
| Unless the scale is waterproof do not spill water or immerse in water | |
| Avoid placing the scale near a heater | It could cause a fluctuation to the indicator reading |
| Always make sure to use a Kilotech approved adapter | |
| Do not drop the scale or subject to sudden shock | |
| Do not drag the scale | |
| Avoid exposing to other electromagnetic devices | These devices emit RF and can cause unstable readings. If your scale should perform poorly, try moving the scale to a different room or location |
| Ensure that the scale is level | A scale used on an uneven surface may provide an unstable reading |
| Scale should be used within stated temperature & humidity limits | |
| | |

Specifications

| | Non Legal | Non Legal | Legal | Non Legal | Legal | Non Legal | Legal |
|---|--|--|--------|--|--------|--|--------|
| Item Number | 851709 | 851330 | 881330 | 851332 | 881332 | 851334 | 881334 |
| Product Name | KIN 500 | KWS 2200-15 | | KWS 2200-30 | | KWS 2200-60 | |
| Capacity | Programmable | 15 kg / 30 lb | | 30 kg / 70 lb | | 60 kg / 150 lb | |
| Graduation | Programmable | 0.005 kg / 0.01 lb | | 0.01 kg / 0.02 lb | | 0.02 kg / 0.05 lb | |
| Weighing Modes | Kg, lb, lb:oz, %, pcs | kg, lb | | kg, lb | | kg, lb | |
| LCD Indicator | 1" high, 6 ½ digits | | | | | | |
| Backlight | Programmable | | | | | | |
| Auto Power Off | Programmable | | | | | | |
| Power | 4 x 1.5 V DC "AA", 120 V AC to 6 V DC adapter, Low battery signal. Adapter included, batteries not included. | | | | | | |
| Dimensions | 89 x 305 x 45 mm 3.5" x 12" x 1.75" | 35.25 x 41.28 x 19.69 cm 13 7/8" x 16 1/4" x 3 1/4" | | 35.25 x 41.28 x 19.69 cm 13 7/8" x 16 1/4" x 3 1/4" | | 35.25 x 41.28 x 19.69 cm 13 7/8" x 16 1/4" x 3 1/4" | |
| Operating Temperature / Humidity | -10° C ~ 40° C / 14° F ~ 104° F / <90% RH non-condensing | | | | | | |
| RS232 | Yes | | | | | | |
| Checkweighing | HI/LO/OK annunciate & alert buzzer | | | | | | |
| Approved Measurement Canada & NTEP | AM 5898 CC 13-016 Max 5000 count | | | | | | |

Specifications

| | Non Legal | Non Legal | Non Legal | Non Legal |
|---|--|-------------------------|-------------------------|--------------------------|
| Item Number | 851313 | 851314 | 851315 | 851317 |
| Product Name | KWS CY-60 | KWS CY-150 | KWS CY-300 | KWS VET 250 |
| Capacity | 60 kg / 132 lb | 150 kg / 330 lb | 300 kg / 660 lb | 250 kg / 500 lb |
| Graduation | 0.02 kg / 0.05 lb | 0.05 kg / 330 lb | 0.1 kg / | 0.2 lb |
| Weighing Modes | kg, lb | kg, lb | kg, lb | kg, lb |
| LCD Indicator | 1" high, 6 ½ digits | | | |
| Backlight | Programmable | | | |
| Auto Power Off | Programmable | | | |
| Power | 4 x 1.5 V DC "AA", 120 V AC to 6 V DC adapter, Low battery signal. Adapter included, batteries not included. | | | |
| Dimensions | 45 x 45 cm 18" x 18" | 61 x 61 cm 24" x 24" | 76 x 76 cm 30" x 30" | 61 x 107 cm 24" x 42" |
| Operating Temperature / Humidity | -10° C ~ 40° C / 14° F ~ 104° F / <90% RH non-condensing | | | |
| Input | X | X | X | X |
| RS232 | X | X | X | X |
| Checkweighing | HI/LO/OK annunciate & alert buzzer | | | X |
| Approved Measurement Canada & NTEP | X | X | X | X |

Unpacking

- Remove the scale from the box and place it on a firm, level surface.
- Avoid locations with rapid temperature changes, excessive dust, moisture, air currents, vibrations, electromagnetic fields, heat or direct sunlight.
- Adjust the leveling feet until the bubble is centered in the circle of the level indicator (located on the front panel).



- NOTE: Ensure that the scale is level each time its location is changed.
- If the scale will be stored or transported in the future, save the packaging material to ensure the best possible protection for the scale.
- There is no leveling bubble on KIN 500


Contents

- Scale or indicator
- 120 V AC to 6 V DC adapter
- Manual

Dimensions


Front View

Left View



Right View

Back View




Power

If 4 x AA size alkaline batteries are used and all the LCD display segments are flashing and “Lo.bAt” is displayed, this will prompt you to replace the batteries immediately, otherwise, it will turn off automatically in 10 seconds.

AC Adapter: 6VDC 500mA, with central negative:



Display & Keypad Definitions



Turn on when scale is stable



Turn on when scale is at zero point and the gross weight is 0

NET

Turn on when net weight is displaying, and the tare weight is not 0; turn off when gross weight is displaying

TOTAL*

Turn on when display data is total times or total of weight, pieces or percentage

lb

Turn on when measure unit is lb or lb:oz

oz

Turn on when measure unit is oz or lb:oz

kg

Turn on when measure unit is kg

%*

Turn on when in percentage weighing mode, measure unit is %

Pcs*

Turn on when in counting mode, measure unit is pieces

BMI

Turn on when working in BMI mode

PEAK

Turn on when in working in HOLD mode and HOLD type is PEAK-HOLD

HOLD

Turn on and flashing/not flashing: working HOLD mode and displaying number is/isn't live

HI*

Turns on when data compare is enable and current data (weight, pieces or percent) is over its upper setting limitation

OK

Turns on when data compare is enable and current data (weight, pieces or percent) is between its high limitation and low limitation

LO*

Turn on when data compare is enable and current data (weight, pieces or percent) is below



Turn on when battery is used or charged

*This function is not used on the Vet Scales

Key Descriptions

Please note that this is a general description of the functions. Some of the keys described below might not be available on your scale. The key examples in this manual are included solely for illustrative purposes. Color or shape of icon might be different.



ZERO / ON/OFF

This key is used to power the scale on and off.

Return to Zero


The zero key can be used to correct a deviation from zero. Press the Zero key to return to a zero value.

The most common cause of a zero deviation is debris on the platter, leaving objects on the platter for excessive periods of time, or near empty battery.




TARE / PRESET

The TARE key is used to deduct the weight of the empty container. It is deducted from gross weight before completing a transaction. Place the container on the scale and when the reading is stable, press TARE. The screen will read 0. TARE will appear on the screen. Now add the products to the container to get their true weight. To remove the TARE function, remove the item with its container and press TARE again. Now the TARE function is cancelled. The range of TARE is up to its maximum capacity.



UNIT/DATA

The Units key is used to toggle between the available units on the scale.



*not applicable for the veterinarian scale

ACC/TOTAL

Is used to accumulate and calculate the total weight.



*not applicable for the veterinarian scale

PRINT/FUNC

It is used to transmit the data over the communication port.



HOLD /SETUP

Peak hold is used to keep the highest value on display when weighing a dynamic load (example: livestock).

Summary of Keys / Functions

Note:

Normally, to use the secondary function of a key, it must be depressed for more than 3 seconds.

| Key | Status | Function |
|---|--|---|
| <u>HOLD</u> <u>SETUP</u>  | Weighing/Counting/Percent, press down < 3s | Enter or exit HOLD mode |
| | Weighing/Counting/Percent, press down > 3s | To enter setup mode |
| | Input data mode, press down > 3s | To input decimal point |
| | Input data mode, press down < 3s | Return to last sub-menu |
| | Menu selection mode | Return to last sub-menu |
| <u>PRINT</u> <u>FUNC</u>  *not used for Vet scale | Weighing/Counting/Percent, press down < 3s | Output data to serial communication port |
| | Weighing/Counting/Percent, press down > 3s | Select working mode: weighing, counting or percent |
| | Input data mode | The digit on flashed position add 1 |
| | Menu selection mode | To last item of current menu |
| <u>ACC</u> <u>TOTAL</u>  *not used for Vet scale | Weighing/Counting/Percent, press down < 3s | To add up current weight/pieces/percentage to memory, display times and total of accumulation |
| | Weighing/Counting/Percent, press down > 3s | To display times and total of accumulation |
| | Input data mode | The digit on flashed position subtract 1 |
| | Menu selection mode | To next item of current menu |
| <u>UNIT</u> <u>DATA</u>  | Weighing mode, press down < 3s | Change weighing units |
| | Counting mode, press down < 3s | To enter getting piece weight |
| | Percent mode, press down > 3s | Set the percentage weight (keypad or platter) |
| | Weighing/Counting/Percent, press down < 3s | Set the HI/LO |
| | Display date or time mode, press down > 3s | To set current date or time |
| | Input data mode | Rotate the flashed position from left to right |
| <u>TARE</u> <u>PRESET</u>  | Weighing/Counting/Percent, press down < 3s | Tare function |
| | Weighing/Counting/Percent, press down > 3s | To input pre-set tare weight at selected weight unit |
| | Input data mode or Menu selection mode | To confirm input data or current item selection |
| | Display ADC code | To confirm current menu |
| <u>ZERO</u> <u>ON/OFF</u>  | Power off mode | Power on |
| | Weighing/Counting/Percent, press down < 3s | Zero function |
| | Weighing/Counting/Percent, press down > 3s | Power off |
| | Input data mode | Ignore modification |
| | Menu selection mode | Prepare to exit from current working mode |

Normal Weighing Mode

Note : During keypad operation, to get to the second function of a key, press it down for more than 3 seconds. To input data or select menu, use the navigation keys to enter.

Power on scale:

When the scale is off, short press the ON/OFF key to turn the scale on.

Power off scale:

When the scale is on, long press the ON/OFF key to turn the scale off.

Change working mode:

Long press the FUNC key, then use arrows to choose and confirm to enter into weighing mode.

Enter to or exit from the HOLD mode:

Press the HOLD key.

ZERO:

When the weight is stable and within the zero range, press the ZERO key to set the new zero point.

TARE: When the gross weight is big than zero, and the scale is stable, press the TARE key. The indicator will show a net weight of zero and the NET annunciator will be lighted.

Preset tare weight: Long press the PRESET key, Pr. Tare will show, and the TARE annunciator flashes, it means it is in preset TARE weight mode, use arrows to input the tare weight, and its unit is the same as the unit that it used before, there's no limitation to preset tare weight, but it should be larger than zero. After input of a tare weight, "NET" annunciator will be lighted.

Clear tare weight: Remove any weight from the platform. Wait until the scale is stable. Short press the TARE key.

Change Weight UNIT: Short press UNIT key to select kg, lb or lb:oz unit. Note that under some conditions, lb:oz is not available.

Error Codes

| | |
|---------|---|
| 0----- | Zero is over the setting range |
| 0----- | Zero point is below the setting range |
| Ad----- | Signal to ADC is over max. range |
| Ad----- | Signal to ADC is below min. range |
| ----- | Weight is over upper limitation, or display data is over limitation |
| ----- | Weight is below lower limitation |
| EEP.E1 | CONFIG or CAL parameters are not correctly set |
| EEP.E2 | USER parameter is not correctly set |
| Lo.bAt | Battery voltage is lower than setting |

Programming Symbols

| | |
|---------|--|
| CAP.--- | Next displaying content is Capacity |
| CAP.ER | Capacity parameters are not correct |
| CAL.Px | Calibration on point(x) |
| CAL.OFF | Calibration Seal Switch is on OFF position |
| CAL.ON | Calibration Seal Switch is on ON position |
| CAL.Er | Calibration error, maybe input data or loaded weight is incorrect, unstable, un-linear |
| CAL.End | Calibration is ended |
| OFF | Power OFF the indicator |
| STB.ER | Unstable scale |
| AC.xxxx | Number of accumulations |
| PR.TARE | To Preset TARE weight |
| COMP | Enter into COMPARE data mode |
| HIGH | Input HIGH value |
| LOW | Input LOW value |
| INP.PCS | Input # of weighted goods |
| UNIT.KG | Unit kg is selected |
| UNIT.LB | Unit lb is selected |